

Amendments to the Drawings:

The Applicants submit the enclosed forma drawings. It is respectfully submitted that these drawings in responsive to the objections provided in PTO-948 mailed October 9, 1997.



Formal Drawings

Forty-one (41) sheets

Inventors: Asher Gil, et al.

SN 08/720,927

Ex. E. Cosimano

Group Art Unit: 3629

RECEIVED


OCT 14 2004

GROUP 3000

CERTIFICATE UNDER 37 CFR 1.8(a)

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner of Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on October 4, 2004.

Laura Barrow







RECEIVED

OCT 7 2004

GROUP 3800



REPLACEMENT SHEET



RECEIVED
OCT 14 2004
GROUP 3600

FIG. 2A



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600





FIG. 2C

OCT 07 2004
PATENT & TRADEMARK OFFICE

REPLACEMENT SHEET

O I P E
OCT 07 2004
PATENT & TRADEMARK OFFICE




RECEIVED
OCT 14 2004
GROUP 3600

FIG. 3



REPLACEMENT SHEET



RECEIVED
OCT 14 2004
GROUP 3600

FIG. 4




FIG. 4A

RECEIVED
OCT 14 2004
GROUP 3600



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600





FIG. 4B



REPLACEMENT SHEET



RECEIVED
OCT 14 2004
GROUP 3600

FIG. 4C



REPLACEMENT SHEET




FIG. 4D

RECEIVED
OCT 14 2004
GROUP 3600





FIG. 4E



REPLACEMENT SHEET

RECEIVED
OCT 14 2004
GROUP 3600





FIG. 5

REPLACEMENT SHEET



RECEIVED

OCT 14 2004

GROUP 3600

FIG. 6A




FIG. 6B

RECEIVED
OCT 14 2004
GROUP 3600



REPLACEMENT SHEET




FIG. 6C


RECEIVED

OCT 14 2004

GROUP 3600



REPLACEMENT SHEET




RECEIVED
OCT 14 2004
GROUP 3600

FIG. 7



REPLACEMENT SHEET




RECEIVED
OCT 14 2004
GROUP 3600

FIG. 8A



REPLACEMENT SHEET





RECEIVED


OCT 14 2004

GROUP 3600

FIG. 8B




REPLACEMENT SHEET




RECEIVED
OCT 14 2004
GROUP 3600

FIG. 8C




REPLACEMENT SHEET




RS-232C PORTS 64 PIN

P4 PRINTER 4



DP9P

PRINTER 1
P1 DCE




RECEIVED
OCT 14 2004
GROUP 3600

DP9P

PRINTER 2


P2



DP9P

PRINTER 3

P3




DP9P

FIG. 9



REPLACEMENT SHEET



RECEIVED
OCT 14 2004
GROUP 3600

FIG. 10

PI ELECTRONICS CORPORATION
MADE IN USA
SIGNAL DISTRIBUTION BD
COPYRIGHT 1991



RECEIVED

OCT 14 2004

GROUP 3000




FIG. 11A



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600




FIG. 11B




REPLACEMENT SHEET

RECEIVED

OCT 14 2004


GROUP 3600






OCT 14 2004

GROUP 3600





OCT 14 2004

GROUP 3600




FIG. 13B



RECEIVED

OCT 14 2004

GROUP 3000




FIG. 14A



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600





FIG. 14B



REPLACEMENT SHEET





FIG. 15

RECEIVED
OCT 14 2004
GROUP 3600



REPLACEMENT SHEET



RECEIVED


OCT 14 2004

GROUP 3600

FIG. 16A



REPLACEMENT SHEET




RECEIVED
OCT 14 2004
GROUP 3600

FIG. 16B



REPLACEMENT SHEET



RECEIVED
OCT 14 2004
GROUP 3600

FIG. 17A



REPLACEMENT SHEET

RECEIVED
OCT 14 2004
GROUP 3600





FIG. 17B



REPLACEMENT SHEET



RECEIVED

OCT 14 2004

GROUP 3600

FIG. 18



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600




FIG. 19



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600





FIG. 20



REPLACEMENT SHEET




RECEIVED
OCT 14 2004
GROUP 3600

FIG. 21



REPLACEMENT SHEET



RECEIVED
OCT 14 2004
GROUP 3000

FIG. 22



REPLACEMENT SHEET

RECEIVED

OCT 14 2004

GROUP 3600




FIG. 23